

Firmware configuration Matrix

T2000ADSB	Date of Release	Main Board	Display Assembly	GPS
1.0.0	9 March 2023	1.0.0	1.0.0	1.0.0
1.0.1	13 March 2023	1.0.1	1.0.1	1.0.0
1.0.2	13March 2023	1.0.2	1.0.1	1.0.0
1.0.3	18 August 2023	1.0.3	1.0.3	1.0.0

1.0.0 Initial Production Release

1.0.1 Changes:

- a. Fixes incorrect characters in variables holding the Flight and Aircraft Ids. Did not affect the message transmitted but complicated entry.
- b. Fixes No Comm error message that appeared during start up.

1.0.2 Initial Customer Release. Changes:

a. Fixes a bug with velocity where it would occasionally lag and then catch up.

1.0.3 Changes:

- a. Fixes bug whereby occasionally the operational status message was not transmitted.
- b. Fixes bug where Mode A/C was not suspended automatically on the ground.
- c. Fixes bug in remote ident.
- d. Added GPS FW updating capability, improved FW updating robustness.
- e. Added BLE support for app including barometric correction and version information.
- f. Add unit operating and inflight timers.
- g. Adds feature to power down external encoder when stationary on the ground.